PROGRAM DIRECTIVE

Program Directive <u>A-51</u>
Issued <u>August 10, 1979</u>
Revised <u>March 9, 2001</u>

SUBJECT: Guarding: Power Transmission Belts

AFFECTED CODES/

DIRECTIVES: OAR 437-02-1910.219(e)(1)(i) to 1910.219(o)(3)(ii); OSHA Instruction

STD 1-12.14, and IM-88-12

PURPOSE: To provide clarification of the application of "enclosed" and "fully

enclosed" as applying to power transmission belts, and guarding by

location.

BACKGROUND: Application of "enclosed" and "fully enclosed" has been interpreted to

mean that all four sides of a power trans- mission belt must be covered by an enclosure. This application has been enforced even when guarding by location has been accomplished by the belts running close enough to walls

or other objects to prevent exposure to employees.

ACTION: A. When there is no employee exposure (past, present, or future) to power transmission belts because they are naturally guarded by

location, then no enclosure or guarding is required.

B. "Enclosure," as used in 1910.219(e)(3)(ii), for vertical and inclined belts means only that portion of a belt within 7 feet of the floor is

required to be enclosed by a guard.

C. "Fully enclosed" applies to the sides of a power transmission system not guarded by location as described in 1910.219(e)(1)(i),

which includes both runs of a horizontal belt, pulley or flywheel (small units with slightly inclined belts are included in this

category).

EFFECTIVE

DATE: This directive is effective immediately and will remain in effect until

cancelled or superseded.

Page 1 A-51