Power Generation, Transmission, and Distribution Stakeholders Meeting Minutes June 11, 2014 8 a.m. - noon

Attendees:

Sue Joye – Oregon OSHA
John Gander – DEC
Ron Dubbs – Emerald PUD
Jeff Wilson – Oregon OSHA
Tracy Harness – NW Line NECA
Ward Andrews – Wilson Construction
Robert Clarkson – IBEW 125

Mike Scarmiwach – IBEW 659 Banjo Reed – IBEW 659 Gary Boswell – PGE Mark Maguire– EWEB Mark Rettmann – Oregon PUC Stuart Sloan – Consumers Power Peg Munsell – Oregon OSHA Stephanie Ficek – Oregon OSHA

The group approved the minutes from the June 4, 2014 meeting.

Jeff Wilson reported on the subcommittee's work on the following rules:

- **437-003-0140 Working Foreman Keep**
- **437-003-0145 General Keep**
- 437-003-0150 Foreman as Safety Watcher Keep
- 437-003-0290 Hot Sticks or Other Protective Devices Keep
- 437-003-0295 Adequate Protection Keep
- 437-003-0450 Two-Worker Rules Remove
- 437-003-0120 More Than 750 Volts Change title to 600 volts. Keep remove (1).

The group picked up in Division 3/V at 437-003-0565 and discussed if we will keep the Oregon-initiated rule or adopt the federal rule.

437-003-0565 Dead End Towers Ward will talk to Harvey

437-003-0570 Wire Rope Keep

437-003-0575 Ladders Remove

437-003-0580 Strength Check Remove

437-003-0585 Route Check Remove

437-003-0590 Equipment Check Keep – change heading to "Equipment Use"

437-003-0595 Platform Use Keep

437-003-0610 Proximity to High Voltage Remove

437-003-0250 Housekeeping Remove

437-003-0605 Qualified Supervision Keep – take out the word "especially"

437-003-0615 Positive Control Remove

437-003-0620 Removing Conductors Keep – take out the first sentence. Change the title to "Replacing Conductors"

437-003-0625 Pulling Keep

437-003-0630 Bare Conductors Remove

The group discussed the *proposed rewrite for* **437-003-0485** *Three Phase Line that Mark Rettmann submitted.* We came up with the following language.

While working on transmission circuits de-energized under clearance conditions with three phase mechanical shorts and grounds established at the lowest impedance available location. Workers may perform work on one phase of a three phase transmission line after establishing an equipotential zone that includes the phase being directly worked on. The phases outside the equipotential zone are to be treated as energized and MAD observed, unless they become part of the equipotential zone.

437-003-0635 Stringing Conductors Keep

437-003-0640 Sleeves Keep – add "unless appropriate safeguards are taken" at the end.

437-003-0645 Reel Tender Keep – table possibly changing language from lineman to qualified worker. Once we've settled on the language, we will look at combining 635 and 645.

437-003-0650 Reel Tending Equipment Remove

437-003-0655 Equipment Secured Keep

TREE TRIMMING

437-003-0720 CPR Training Table – Jeff Wilson will talk to the tree trimmers.

437-003-0725 Rescue Training Table – Jeff Wilson will talk to the tree trimmers.

437-003-0707 Chipper equipment and operation Table – Jeff Wilson will talk to the tree trimmers.

437-003-0770 Barriers, Guards, Warning Signs Remove

437-003-0775 Guarding Required Before Entering Remove

437-003-0780 Test for Flammability Remove

437-003-0785 Illumination Remove

Meeting Adjourned: 11:55 a.m.

Next Meeting: Wednesday, June 18, 2014, 8 a.m. – noon.